

SPECIAL AIRWORTHINESS INFORMATION BULLETIN

Aircraft Certification Service
Washington, DC



U.S. Department
of Transportation

**Federal Aviation
Administration**

NM-05-68
July 8, 2005

<http://www.faa.gov/aircraft/safety/alerts/>

This is information only. Recommendations aren't mandatory.

Introduction

This Special Airworthiness Information Bulletin alerts you, owners and operators of **certain Transport Category Airplanes (listed in Table 1)**, that the design is such that mechanical advantage enables the capability of opening the exit when significant differential pressure exists between the cabin and the outside. In some cases, this differential may be sufficient to push the person operating the exit through the exit opening. Airplanes with this potential include, but aren't limited to, the following aircraft in Table 1.

TABLE 1

Manufacturer	Model
Aerospatiale (S.N.I.A.)	ATR42
	ATR72
	SN-601 "Corvette"
Airbus (Industries)	A318
	A319
	A320
	A321
	A330
Boeing Company	A340
	737-600/-700/-800/-900
	Overwing exit
	747-300/-400 Upper deck exit
Bombardier Inc. (Canadair)	BD-100-1A10 (Challenger)
	BD-700-1A10 (Global Express)
	CL-600-1A11 (CL-600 series)

Bombardier Inc. (continued)	CL-600-2C10 (RJ 700 series)
	CL-600-2D24 (RJ 900 series)
	DHC-3
	DHC-4
	DHC-6
Cessna Aircraft Company	DHC-7
	550/560
	560XL
	650
Dassault- Aviation	750
	Fan Jet Falcon
	Mystere-Falcon 20
	Mystere-Falcon 200
	Mystere-Falcon 50
	Mystere-Falcon 900
	Falcon 900EX
	Falcon 2000
AvCraft Aerospace GmbH (Fairchild Dornier)	Falcon 2000EX
	328-100
	328-300
Fokker Services	F.28
	F.28 Mark 0070/Mark 0100
	Airstair door
Learjet Inc. (Gates)	24
	25
	31
	35
	36
	55
	60

Background

The National Transportation Safety Board (NTSB) has recommended that manufacturers design fuselage doors on future airplanes so that they can only be opened when there is limited differential pressure between the cabin and the outside. This recommendation was based on incidents and accidents where persons were pushed through an exit when it was opened under high differential pressure. We have issued airworthiness directives to address the airplanes on which this occurred because of the severity of the condition.

The NTSB also recommended that operators implement a way of notifying persons that the exit can be opened with differential pressure and to exercise caution.

During our investigation, we concluded that the majority of airplanes on which opening with significant differential pressure is possible are the smaller transports, which have several mitigating features.

- They are low to the ground, they have relatively small cabin volumes, and will thus equalize pressure very quickly.
- They are usually operated by persons familiar with the airplane. Even so, there is some potential for injury and we want to make you aware of it.

- In the other airplanes, the exits are either primarily emergency exits and aren't used for boarding or loading of supplies, or are already equipped with an indication for opening in non-emergency conditions.
- We expect that the situation would occur only rarely as there is generally only significant differential pressure on the ground following failure(s) in the cabin air pressurization or venting systems.

Recommendation

We agree with NTSB and recommend that you implement a means to notify persons that doors or exits on the identified airplanes can be opened with significant differential pressure and that in the event you feel resistance in opening the door, you should proceed with caution. For example, you may elect to install placards or indication systems near or on the affected exits.

For Further Information Contact

Jeff Gardlin, Aerospace Engineer, FAA
Transport Airplane Directorate, Standards
Staff, Airframe/Cabin Safety Branch, 1601
Lind Ave. SW, Renton, Washington 98055;
phone: (425) 227-2136; fax: (425) 227-1149;
email: jeff.gardlin@faa.gov